

ORIG
UNIT
EXT
DATE: 4 SEPT 1963

~~SECRET~~

1	COMMO/OSA	9
2	"	10
3	AD/OSA	11
4	D/PA/OSA	12
5	OD/OSA	13
6	"	14
7	INTEL/OSA	15
8	RB/OSA	16

DEFERRED	PRIORITY	INITIALS
<input checked="" type="checkbox"/> ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO: [REDACTED]
FROM: DIRECTOR
CONF: OSA 1-15
INFO:

EDD [REDACTED]
WER [REDACTED]
RDO [REDACTED]
RLP [REDACTED]
KB [REDACTED]
SHI [REDACTED]
PGS [REDACTED]

OUT 18275

TO: [REDACTED] INFO

CITE [REDACTED]

2600

IDEALIST COMMO

25 YEAR RE-REVIEW

ODINCH TECH FEEDBACK MSN 6066 [REDACTED] FOLLOWS:

1. 6066 WAS MOST EXTREME EXAMPLE OF "ERRATIC SCAN" TO DATE. RCVR TWO REPORTED ERRATIC FOR ENTIRE RECORDING TIME. RCVR ONE SCANNED NORMAL FOR FIRST 15 MIN, AND WENT ERRATIC FOR REMAINDER. TRACK THREE REPORTED ERRATIC THRUOUT MISSION.

2. LOCK-ON TIME ALL RCVRs ~~WENT~~ NORMAL. VOICE INTERCEPTS WERE GOOD QUALITY, BUT SPARSE (PROBABLY PARTIALLY DUE TO APPARENT LOSS OF SENSITIVITY WHICH ACCOMPANIES THE ERRATIC SCANNING).

3. QUERY: IS [REDACTED] DUPE OF MSN 6066 AVAILABLE AT [REDACTED] OR IS IT POSSIBLE ~~FOR~~ TO OBTAIN ORIGINAL FROM [REDACTED] FOR TECH ANALYSIS BY [REDACTED] TECHS? WOULD APPRECIATE YOUR COMMENTS ON NATURE AND CAUSE OF THE REPORTED "ERRATIC SCAN".

END OF MESSAGE

INTEL/OSA [REDACTED]
COORDINATING OFFICERS

CHIEF, COMMO/OSA

RELEASING OFFICER

~~SECRET~~

GROUP 1
Excluded from automatic
downgrading and
declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.